

References

The **references** listed below refer to the numerical superscripts included in the April-May-June 2010 issue of *The Q-Net Monthly*, which can be downloaded at: www.myendosite.com/htmlsite/2010/VAOIG_PR.pdf

1. Veterans Administration Office of Inspector General. Health Inspection. Patient safety issues: VA Caribbean Healthcare System. Report No. 09-03055-103. Issued: March 16, 2010. San Juan, Puerto Rico. Pages 1-13.
2. Veterans Administration Office of Inspector General. Health Inspection: Use and reprocessing of flexible fiberoptic endoscopes at VA medical facilities. Report No. 09-01784-146. Issued: June 16, 2009. Pages 1-45.
3. Veterans Health Administration. VHA Directive 2008-002. Disclosure of adverse events to patients. Dated: January 18, 2008. Department of Veterans Affairs. Washington, DC.
4. Centers for Disease Control and Prevention. Guideline for disinfection and sterilization in healthcare facilities, 2008.
5. Kac G, Podglajen I, Si-Mohamed A, et al. Evaluation of ultraviolet C for disinfection of endocavitary ultrasound transducers persistently contaminated despite probe covers. *Infect Control Hosp Epidemiol* 2010;31:165–170.
6. Nelson DB, Muscarella LF. Current issues in endoscope reprocessing and infection control during gastrointestinal endoscopy. *World J Gastroenterol* 2006;12:3953-64.
7. Muscarella LF. Dear Los Angeles Times: the risk of disease transmission during gastrointestinal endoscopy. *Gastroenterol Nurs* 2004 Nov-Dec;27(6):271-8.
8. American Society for Gastrointestinal Endoscopy. Multi-society guideline for reprocessing flexible gastrointestinal endoscopes. *Gastrointest Endosc* 2003;58:1-8.
9. Olympus Corporation. Olympus EVIS EXERA II GIF/CF/PCF Type 180 Series Reprocessing Manual.
10. DiazGranados CA, Jones MY, Kongphet-Tran T, et al. Outbreak of *Pseudomonas aeruginosa* infection associated with contamination of a flexible bronchoscope. *Infect Control Hosp Epidemiol* 2009 Jun;30(6):550-5.
11. Ramsey AH, Oemig TV, David JP, et al. An outbreak of bronchoscopy-related *Mycobacterium tuberculosis* infections due to lack of bronchoscope leak testing. *Chest* 2002 Mar;121(3):976-81.
12. Karl Storz Endoscopy America Inc.. Instruction manual. Flexible rhino-laryngo-fiberscope 11003BC1, 11101RP2, 11101SK2. 2009. 1-28.
13. Guidance for Industry and FDA Staff. Information for Manufacturers Seeking Marketing Clearance of Diagnostic Ultrasound Systems and Transducers. Document issued on: September 9, 2008.

Also, refer to the CDC's "Guideline for Disinfection and Sterilization in Healthcare Facilities, 2008," which states that: "... sterile transvaginal ultrasound probe covers have a very high rate of perforations even before use."

14. Rutala WA, Gergen MF, Weber DJ. Disinfection of a probe used in ultrasound-guided prostate biopsy. *Infect Control Hosp Epidemiol*. 2007 Aug;28(8):916-9.
15. Lessa F, Tak S, Devader SR, Goswami R, Anderson M, Williams I, Gensheimer KF, Srinivasan A. Risk of infections associated with improperly reprocessed transrectal ultrasound-guided prostate biopsy equipment. *Infect Control Hosp Epidemiol*. 2008 Apr;29(4):289-93.
16. Muscarella LF. [Recommendations to resolve inconsistent guidelines for the reprocessing of sheathed and unsheathed rigid laryngoscopes](#). *Infect Control Hosp Epidemiol*. 2007 Apr;28(4):504-7.
17. Muscarella LF. Prevention of disease transmission during flexible laryngoscopy. *Am J Infect Control*. 2007 Oct;35(8):536-44.
18. John D. Daigh, Jr., M.D., CPA. Assistant Inspector General for Healthcare Inspections Office of Inspector General. U.S. Department of Veterans Affairs. Statement to Congress: "Endoscopy procedures at the VA: What happened, what has changed?" Date: June 16, 2009. (Also see: William Duncan, M.D. Associate deputy under secretary for health, quality, and safety. Veterans Health Administration. Department of Veterans Affairs. Statement to Congress: Date: June 16, 2009.)
19. Food and Drug Administration. Preventing Cross-Contamination in Endoscope Processing. Safety Communication from FDA, CDC, and the VA. November 19, 2009.
20. Food and Drug Administration. Letter to Endoscope Manufacturers: Possible Misbranding of Reusable Devices Labeled for Reprocessing by the STERIS System 1 Processor. February 22, 2010.
21. Food and Drug Administration. Warning letter. May 15, 2008. CIN-08-5964-15
22. Muscarella LF. The STERIS System 1. The Q-Net Monthly 2009 Jul-Aug-Sept 2009;15(7-9):13-18S2.
23. Bronowicki JP, Venard V, Botte C, et al. Patient-to-patient transmission of hepatitis C virus during colonoscopy. *N Engl J Med* 1997 Jul 24;337(4):237-40.
24. Muscarella LF. Adulterated and misbranded devices: A position statement. The Q-Net Monthly 2009 Oct-Nov 2009;15(10-11):19-22S1. (Also see: Food and Drug Administration. Emergency Use of Unapproved Medical Devices. Updated: 10/26/2009.
25. Code of Federal Regulations Title 21. Food and Drugs. Chapter 9. Federal Food, Drug, and Cosmetic Act. Subchapter V—Drugs and Devices. Part A--Drugs and Devices. Sec. 352. Misbranded drugs and devices. (See item "o.")
26. Department of Veterans Affairs (VA). Office of Patient Care Services. Manual M-2, Part IV, Chapter 6. Infectious Diseases. Policy 6.01. Washington, D.C.
27. Veterans Health Administration. Improper set-up and reprocessing of flexible endoscope tubing and accessories. Patient safety alert. AL09-07 December 22, 2008.
28. Veterans Administration Office of Inspector General. Health Inspection. Alleged mismanagement of resources and patient safety issued. VA Northern Indiana Health Care System. Report No. 09-02346-90. Issued: March 2, 2010. Fort Wayne and Marion, Indiana. Pages 1-19 .

29. Department of Veterans Affairs. VA Tennessee Valley Healthcare System. Standard Operating Procedure: "Steris One Sterilizer – operation and maintenance." Service memorandum 90-03-21, dated March 18, 2008. (*Also see:* [A] Standard Operating Procedure: Cleaning, disinfecting/sterilization of flexible ERCP scopes. Service memorandum 90-03-14, dated January 2, 2009. [B] Standard Operating Procedure: Cleaning, disinfecting/sterilization of flexible endoscopes. Service memorandum 90-07-14, dated February 7, 2008. [C] Standard Operating Procedure: Cleaning, disinfecting/sterilization of flexible sigmoid scopes. Service memorandum 90-03-14, dated January 2, 2009.
30. Veterans Health Administration. Transrectal ultrasound transducer assembly, models 8808 and 8551, manufactured by B-K Medical Systems,. Inc. Wilmington, MA. Patient safety alert. AL06-011 April 3, 2006.